

Work Order ID 136896

Wednesday, September 16, 2015 3:34:31 PM

Ship Oct 7/15
136896

Page 1

Item ID: D3230-041 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Basket Wedge Assembly
 Start Date: 9/17/15 Start Qty: 1.00 *1* Cust Item ID:
 Required Date: 10/02/15 Req'd Qty: 1.00 *1* Customer:
 Reference:

Approvals: Process Plan: Sck Date: 0150916 Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3230	D								

110

110

Large Fab

Large Fab

Large Fab

Memo

1-Cut 3/4 x 3/4 square tubing as per Dwg D3230

2- Drill and c/sink holes

3- Cut mesh as per dwg

4 -Deburr & Remove all Markings From Material

5-Weld bushings and fabricate basket wedge assembly as per D3230

6- USE DT10137 TO LOCATE BACK HINGE AS PER DWG.

LOOK AT DWG FRONT MESH MUST BE WELDED INSIDE

A/R SS ROD Batch: 4131417

0.00

0.00

DAS
43
9-89

OCT 06 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐					
		OTHER : ☐							

Wednesday, September 16, 2015 3:34:31 PM

Page 2

Reference:

Stop ***NR2***

[illegible]

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		OTHER : ☐					

Work Order ID 136896***136896***

Page 3

Item ID: D3230-041

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Basket Wedge Assembly

Start Date: 9/17/15 Start Qty: 1.00

1

Cust Item ID:

Required Date: 10/02/15 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

140

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

0.00

140

Powdercoat

m 132729

Memo

0.00

Powder Coating

1ST COAT:

START TIME:

OVEN TEMPERATURE:

FINISH TIME:

**** if necessary****

2ND COAT:

START TIME:

OVEN TEMPERATURE:

FINISH TIME:

1 15-10-6 34 98

150

QC3- Inspect Part Finish

0.00

150

QC

Memo

0.00

Quality Control

DAS
38
9-89

OCT 07 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause				FAULT CATEGORY			
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date	☐	Manufacturing Process	☐	OTHER :			
Misidentified	☐	Past Due	☐				

Work Order ID 136896***136896***

Page 4

Item ID: D3230-041

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Basket Wedge Assembly

Stop ***NS2***Start Date: 9/17/15 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 10/02/15 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start ***NR1***
Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
180	Identify as per dwg & Stock Location: _____ Packaging	0.00							
180									
Packaging	Memo	0.00							DAS 10 0-00
Packaging									OCT 07 2015
190	QC21- Final Inspection - Work Order Release	0.00							
190									
QC	Memo	0.00							MLJ OCT 07 2015
Quality Control									

MF-
15-10-07

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		OTHER : _____					

Picklist Print

Wednesday, September 16, 2015 3:34:36 PM

Page 1

Work Order ID: 136896

136896

Parent Item: D3230-041

D3230-041

Parent Item Name: Basket Wedge Assembly

Start Date: 9/17/15

Required Date: 10/02/15

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:D 09-02-25 rev.c as per dwg DD verified by:EC
15.04.14 revD as per dwg DD verified by:JLM IPP Rev:E

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2232-3		Manufactured	No			110	Each	26.0000	2	2			
D2232-3									**		DAS 43 9-89	SEP 25 2015	
Basket Hinge													
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				WA004				26					
					115847			20					
					132731			6					
D2327-3		Manufactured	No			110	Each	9.0000	2	2			
D2327-3									**		DAS 43 9-89	SEP 25 2015	
Spacer Bushing													
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				WA004				9					
					131972			9					
D3759-1		Manufactured	No			110	Each	24.0000	5	5			
D3759-1									**		DAS 43 9-89	SEP 25 2015	
Bushing													
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				WA004				24					
					135756			24					
D4021-9		Manufactured	No			110	Each	36.0000	4	4			
D4021-9									**		DAS 43 9-89	SEP 25 2015	
Bushing													
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				WA004				36					
					120334			2					
					122601			4					
					134919			30					

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause				FAULT CATEGORY			
Environment ☐	Design ☐	Doc/Data ☐	Equip/Tooling ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Handling/Pre ☐	Material ☐	Internal Transport ☐	Tribal Knowledge ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐
LOA ☐	Substation ☐	Past Expiry Date ☐	Misidentified ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
				Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
				Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
				Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
				Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
				Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
				Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
				Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐				OTHER : _____			

Picklist Print

Wednesday, September 16, 2015 3:34:36 PM

Page 2

Work Order ID: 136896

136896

Parent Item: D3230-041

D3230-041

Parent Item Name: Basket Wedge Assembly

Start Date: 9/17/15

Required Date: 10/02/15

Start Qty: 1.00

Required Qty: 1.00

M304EX0.75-16F

Purchased

No

110

sf

408.9522

5.15

5.421053

DAS

43

9-89

SEP 25 2015

M304EX0 75-16F

Expanded Metal Flat SS

**

M132745 → 8.2cf

Location

Loc Qty

Loc Code

WA004

408.9522

M132745

208.8922

M132864

40.06

M132967

160

M304TS0.750W.065

Purchased

No

110

f

881.3500

26

27.36842

DAS

43

9-89

SEP 25 2015

M304TS0 750W 065

304 SQ Tube .75x.75x.065W

**

M132270 → 30.6cf

Location

Loc Qty

Loc Code

WA004

881.35

125513

14

m128495

95.35

m132190

30

m132270

142

m132924

600

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐


Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					

Root Cause			FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date	☐	Manufacturing Process	☐	OTHER :						
Misidentified	☐	Past Due	☐							

8 7 6 5 4 3 2 1

ITEM	QTY	P/N	DESCRIPTION
	X	D3230-041	BASKET WEDGE ASSEMBLY
1	2	D2232-3	HINGE PLATE
2	2	D2327-3	SPACER BUSHING
3	1	D3230-1	RIB
4	1	D3230-2	RIB
5	1	D3230-3	RIB
6	1	D3230-4	RIB
7	4	D3230-5	RIB
8	1	D3230-7	RIB
9	2	D3230-9	SIDE MESH
10	1	D3230-11	FRONT MESH
11	1	D3230-13	RIB
12	5	D3759-1	BUSHING
13	4	D4021-9	BUSHING

△
△



D3230-041 BASKET WEDGE ASSEMBLY
(MESH SHOWN LOCALLY FOR CLARITY)

RELEASED
2015 APR 13
ECN 15-559 A.P.

20150916 JH 136896


D	CHANGE OVERALL LENGTH TO 95.75 (WAS 96.00) TO IMPROVE FIT ON BASKET (REF NCR15-4557), ADD DETAIL G (SH 2), ADD D3230-13, D4021-9 (4 PL)	DB	15.03.26
C	REDESIGN (SEE NCR 09-010); REFORMAT DRAWING TO CURRENT STANDARDS	MB	09.01.27
B	15.75 WAS 16.00; REMOVE D2581; ADD VIEW B-B; D2327-3 ADDED	CB	06.11.10
A	NEW ISSUE	CP	03.10.31
REV.	DESCRIPTION	BY	DATE

- NOTES:
- 1) MATERIAL: N/A
 - 2) FINISH: POWDER COAT ENTIRE ASSEMBLY WHITE (4.3.5.2) PER DART QSI 005 4.3
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
 - 6) IDENTIFICATION: IDENTIFY PER DART QSI 044 6.1
 - 7) WEIGHT: 19.8 lbs
 - 8) WELDING: PER DART QSI 004


APPROVED


DESIGN	CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
DRAWN	DB	
CHECKED	MB	
MFG. APPR.	DD	
APPROVED	HS	
DE APPR.	DS	DRAWING NO. D3230
DATE	15.03.26	TITLE BASKET WEDGE ASSEMBLY
		REV. D
		SHEET 1 OF 5
		SCALE
		NTS
COPYRIGHT © 2003 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS UNDERSTANDING THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.		

8 7 6 5 4 3 2 1




APPROVED	DESIGN	CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
	DRAWN	DB		
	CHECKED	MB	DRAWING NO.	REV. D
	MFG. APPR.	DD	D3230	SHEET 2 OF 5
	APPROVED	HS	TITLE	SCALE
	DE APPR.	DS	BASKET WEDGE ASSEMBLY	NTS
DATE		15.03.26	COPYRIGHT © 2003 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	







D3230-5 RIB




D3230-7 RIB



D3230-9 SIDE MESH



D3230-11 FRONT MESH




D3230-13 RIB


RELEASED
2015 APR 13
ECN 15-559 A.P.

- NOTES:**
- 1) MATERIAL:
D3230-5/-7/-13: AISI 304/316 STAINLESS STEEL SQUARE TUBE, 0.75 X 0.75 X 0.065 WALL
REF. DART SPEC. M304TS0.750W0.065
D3230-9/-11: 3/4-16F EXPANDED STAINLESS STEEL
REF. DART SPEC. M304EX0.75-16F
 - 2) FINISH: N/A
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
 - 6) IDENTIFICATION: N/A
 - 7) WEIGHT: D3230-5 = 0.21 lbs; D3230-7 = 4.55 lbs
D3230-9 = 0.20 lbs; D3230-11 = 1.94 lbs; D3230-13 = 4.56 lbs


APPROVED	DESIGN	CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
	DRAWN	DB		
	CHECKED	MB	DRAWING NO.	REV. D
	MFG. APPR.	DD	D3230	SHEET 4 OF 5
	APPROVED	HS	TITLE	SCALE
	DE APPR.	DS	BASKET WEDGE ASSEMBLY	NTS
	DATE	15.03.26	COPYRIGHT © 2003 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	




DETAIL A D6-2
MESH NOT SHOWN FOR CLARITY
SCALE 4X




DETAIL B D3-2
MESH NOT SHOWN FOR CLARITY
SCALE 4X




DETAIL C B3-2
MESH NOT SHOWN FOR CLARITY
SCALE 4X



DETAIL E C7-2
MESH NOT SHOWN FOR CLARITY
SCALE 8X



DETAIL F C2-2
MESH NOT SHOWN FOR CLARITY
SCALE 8X



DETAIL D B3-2
MESH NOT SHOWN FOR CLARITY
SCALE 4X

RELEASED

2015 APR 13
ECN 15-559 A.P.

APPROVED

DESIGN	CP	DART AEROSPACE LTD	
DRAWN	DB	HAWKESBURY, ONTARIO, CANADA	
CHECKED	MB	DRAWING NO.	REV. D
MFG. APPR.	DD	D3230	SHEET 5 OF 5
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	BASKET WEDGE ASSEMBLY	NTS
DATE	15.03.26	COPYRIGHT © 2003 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	